



HUMIDITY METER, data logger, RS232

Model : YK-90HT

- * Humidity, Temp., Dew point.
- * Humidity range : 10 % to 95 % R.H.
- * Temp. range : 0 °C to 50 °C, 32 °F to 122 °F.
- * 0.01 %RH, 0.01 degree.
- * 1000 data logger point.
- * Optional data transmission software, SW-DL2005.
- * RS-232/USB computer interface.

HUMIDITY METER, +Dew Point + Type K

Model : HD-3008



HUMIDITY/TEMP. METER

Model : PHT-316

- * Humidity : 10% to 95% RH.
- * Temperature : 0 to 50 °C.
- * Temp. unit : °C, °F. internal adjustment.
- * Humidity measurement with fast response time
- * All in one, pen type, easy carryout.
- * Hold function to freeze display value.
- * Build in reverse display button.
- * DC 1.5V battery (UM-4, AAA) x 4.

**Humidity
Dew Point**



HUMIDITY METER, Real time data logger

Model : YK-2005RH

- * Humidity : 10 to 95 %RH, Temp. : 0 to 50 °C, °C/ °F.
- * High capacity, 16,000 data logger point.
- * Real time data logger (record year, month, date, hour, minute, second) .
- * Humidity, Temp., Dew point, type K/J Temp.
- * Resolution : 0.01 %RH, 0.01 degree.
- * Humidity function with very fast response time.
- * Max., Min., Data hold, zero adjust.
- * RS-232/USB computer interface, Jumbo LCD.
- * Optional data transmission software, SW-DL2005.
- * DC 1.5V (UM3, AA) x 4 PCs or DC 9V adapter in.
- * Size : 203 x 76 x 38 mm.



HUMIDITY METER

Model : MY-91HT

- * Measurement : Humidity, Temp., Dew point.
- * Humidity range : 10 % to 95 % R.H.
- * Temp. range : 0 °C to 50 °C, 32 °F to 122 °F.
- * Resolution : 0.01% RH, 0.01 degree.
- * 1000 data logger point.
- * Fast response time, 1,000 point data logger.
- * RS-232/USB, Data hold, Record (Max., Min.).
- * DC 1.5V (UM-4, AAA) battery x 6.



HUMIDITY METER

Model : LM-81HT

- * Humidity : 10 to 95 %RH.
- * Temperature : 0-50.0 °C, °C/°F.
- * Tiny bone shape with light weight and small size.



PRECISION HUMIDITY + TEMP. + DEW POINT

Model : HT-3009

- * 1000 Data logger no., RS-232/USB interface.
- * Resolution : 0.01 %RH, 0.01 degree.
- * 4 sec., fast humidity response time.
- * 2 %RH humidity accuracy, high precision.
- * The best professional hygrometer.
- * Optional data transmission software, SW-DL2005.



HUMIDITY/BAROMETER/TEMP. METER

Model : PHB-318

- * Barometer : 10 to 1100 hPa, mmHg, inHg.
- * Humidity : 10% to 95% RH, Dew.
- * Temperature : 0 to 50 °C, °C/°F.
- * All in one, pen type, easy carryout.
- * Hold, Record (max., min.).
- * DC 1.5V battery (UM-4, AAA) x 4.



33 %RH HUMIDITY CALIBRATOR

Model : RHA-33

75% RH HUMIDITY CALIBRATOR

Model : RHA-75